

## Uszczelnienie zgarniające ZZ



ZZ

Nazwa	d (rys.)	D (rys.)	H (rys.)	h1
ZZ-10	10	16	4,50	3
ZZ-10/1	10	20	8	5
ZZ-12	12	18	6	4
ZZ-12/1	12	22	8	5
ZZ-14	14	20	7	5
ZZ-16	16	22	7	5
ZZ-16/1	16	26	8	5
ZZ-16/2	16	26	10	7
ZZ-18	18	24	7	5
ZZ-18/1	18	28	7	5
ZZ-20	20	28	7	5
ZZ-20/1	20	28	8	5
ZZ-20/2	20	30	7	5
ZZ-22	22	30	7	5
ZZ-22/1	22	32	7	5
ZZ-25	25	33	7	5
ZZ-25/1	25	35	7	5
ZZ-25/2	25	35	8	5
ZZ-25/4	25	35	10	7
ZZ-28	28	36	7	5
ZZ-28/1	28	38	8	5
ZZ-28/2	28	38	10	7
ZZ-28/3	28	40	10	7
ZZ-30	30	40	7	5
ZZ-30/1	30	40	8	5
ZZ-30/2	30	40	10	7
ZZ-32	32	40	7	4
ZZ-32/1	32	40	7	5

<b>Nazwa</b>	<b>d (rys.)</b>	<b>D (rys.)</b>	<b>H (rys.)</b>	<b>h1</b>
ZZ-32/2	32	40	10	7
ZZ-32/3	32	42	7	5
ZZ-32/4	32	42	10	7
ZZ-32/5	32	45	7	5
ZZ-32/6	32	45	10	7
ZZ-35	35	45	7	5
ZZ-35/1	35	45	8	5
ZZ-35/2	35	45	10	7
ZZ-36	36	44	7	5
ZZ-36/1	36	46	7	5
ZZ-38	38	48	10	7
ZZ-40	40	48	7	5
ZZ-40/1	40	50	7	5
ZZ-40/2	40	50	8	5
ZZ-40/3	40	50	10	7
ZZ-40/4	40	52	8	7
ZZ-45	45	53	7	5
ZZ-45/1	45	55	7	5
ZZ-45/2	45	55	10	7
ZZ-45/4	45	56	7	5
ZZ-45/5	45	60	10	7
ZZ-50	50	56	7	5
ZZ-50/1	50	58	7	5
ZZ-50/2	50	60	7	5
ZZ-50/3	50	60	10	7
ZZ-50/4	50	65	10	7
ZZ-55	55	63	7	5
ZZ-55/1	55	65	7	5
ZZ-55/2	55	65	10	7
ZZ-56	56	64	7	3
ZZ-56/1	56	65	10	7
ZZ-56/2	56	66	7	5
ZZ-60	60	68	7	5
ZZ-60/1	60	70	7	5
ZZ-60/2	60	70	10	7
ZZ-63	63	71	7	5
ZZ-63/1	63	73	7	5
ZZ-63/3	63	73	10	7
ZZ-63/5	63	75	10	7
ZZ-65	65	75	7	5
ZZ-65/1	65	75	10	7
ZZ-70	70	78	7	5
ZZ-70/1	70	80	7	5
ZZ-70/2	70	80	10	7
ZZ-75	75	85	10	7
ZZ-80	80	88	7	5
ZZ-80/1	80	90	7	5

<b>Nazwa</b>	<b>d (rys.)</b>	<b>D (rys.)</b>	<b>H (rys.)</b>	<b>h1</b>
ZZ-80/2	80	90	10	7
ZZ-80/3	80	95	7	5
ZZ-85	85	95	10	7
ZZ-90	90	98	7	5
ZZ-90/1	90	100	7	5
ZZ-90/2	90	100	10	7
ZZ-95	95	105	10	7
ZZ-100	100	110	10	7
ZZ-105	105	115	10	7
ZZ-110	110	122	10	7
ZZ-110/1	110	125	10	7
ZZ-115	115	125	10	7
ZZ-120	120	130	10	7
ZZ-125	125	140	12	9
ZZ-130	130	145	12	9
ZZ-135	135	145	10	7
ZZ-140	140	150	10	7